



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB528

Issue Date: 8-21-2026


Effective Date: 8-21-2026

Description/Title:

Change to Solder Feed Drives for FU-500 and HU-200

Comments:

When the FU-500 and HU-200 were introduced (Ref PB416 and PB424), the Solder Feed Drive used to feed the solder was designed to grip the solder by perforating the wire to the flux core. Over time, the blades dull, and when the solder feed is jammed, solder and flux clog the cutting wheel. Due to the design of this part, it was not easy to service and typically required full replacement.



As part of our continual product improvement efforts, the design of the Solder Feed Drive has been changed to make it a serviceable part that can be disassembled for cleaning and allows for individual replacement of the drive wheel, follower wheel, and PTFE guides.

This change will begin to appear, starting with the Solder Feed Drive for 0.3mm diameter solder, as we cycle through our inventory this year. Part numbers for the old design will transition to new part numbers, and once the supply is depleted, the old part numbers will be discontinued.

Part No:

Old Design: BX1000, BX1001, BX1002, BX1003, BX1004, BX1005, BX1006

New Design: BX1076, BX1077, BX1078, BX1079, BX1080, BX1081, BX1082

Specification:

Unchanged. New and Old design are interchangeable.

For more information please visit www.HakkoUSA.com or call 1-800-88-HAKKO (42556)

AHP14 Rev 2025-06



28920 Avenue Williams, Valencia, CA 91355



661-294-0090



HakkoUSA.com