



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB511

Issue Date: 1-20-2026

Effective Date: 1-20-2026

Description/Title:

Firmware v1.10 Update for FX-971

Comments:

This firmware update improves the sleep function by filtering out minor tip temperature fluctuations that may occur while the iron is idle in the iron holder, which resets the timer for sleep mode.

Please visit our online knowledge base at <https://kb.hakkousa.com>, where you can find the firmware download and step-by-step instructions in the Software section.

Part No:

FX971-010, FX971-011

Specification:

Unchanged

For more information please visit www.HakkoUSA.com or call 1-800-88-HAKKO (42556)

